



# Gecko Platform 4.2.0.0 GA

## Gecko SDK Suite 4.2

### December 14, 2022

The Gecko Platform provides infrastructure support for applications developed with higher-level protocols, and it provides an interface with the underlying hardware. It is composed of the following modules:

**CMSIS Device** is a vendor-independent hardware abstraction layer for the Cortex®-M processor series.

**Peripherals** provides a complete peripheral API for all Silicon Labs EFM32, EZR32 and EFR32 MCUs and SoCs.

**Drivers** is the Gecko Platform driver library for EFM32, EZR32 and EFR32 on-chip peripherals. Drivers are typically DMA-based and use all available low-energy features.

**Services** includes common services such as NVM3 and Power Manager.

**CPC (Co-Processor Communication)** provides a library to communicate between two processors using a serial link. CPC is used by the ACP & RCP solutions

**Common** components are used throughout the SDKs.

**Middleware** includes the Capacitive Sensing Firmware Library and the GLIB graphics library, along with Micrium OS stacks like CAN/CANopen, File System, Networking and USB Device and Host.

**Security** includes mbed TLS and other security services.

**Operating System** includes Micrium OS Kernel as well as other things related to Operating Systems such as a CMSIS-RTOS2 layer.

The **Gecko Bootloader** is a code library configurable through Simplicity Studio's IDE to generate bootloaders that can be used with a variety of Silicon Labs protocol stacks. The Gecko Bootloader can be used with EFM32 and EFR32 Series 1 and later devices.

**Machine Learning** includes TensorFlow Lite Micro components, used to run neural network inference, and related preprocessing components.

**Examples** are example applications illustrating platform functionality.

**Boards and External Devices** cover supported hardware.

**Other Gecko Platform Components** regroups changes to documentation, project building and configuration, as well as any other aspects related to Gecko Platform.

**RAIL (Radio Abstraction Interface Layer)** provides a customizable radio interface layer that supports proprietary or standards-based wireless protocols. RAIL use by application protocols such as Silicon Labs Zigbee or Silicon Labs Connect is managed through the stack library. Direct RAIL use is exposed through the Flex SDK.

These release notes cover SDK version(s):

Gecko Platform 4.2.0.0 released December 14, 2022



#### KEY FEATURES

- Support for EFR32xG25 devices
- Support for MGM240Dx modules
- Support for BGM24x modules
- Improved CPC UART drivers reliability
- Many CPC improvements
- Android support for CPCd

#### Security:

- Updates the Mbed TLS library to version 3.2.1, with support for CBAP.
- Updated ITS driver (version 3) for faster performance.
- Updated software support for TrustZone, Evaluation quality

**Contents**

1 CMSIS Device ..... 2

2 Peripherals ..... 3

3 Drivers ..... 4

4 Services ..... 5

5 CPC ..... 6

6 Common ..... 8

7 Middleware ..... 9

8 Security ..... 10

9 Operating System ..... 12

10 Gecko Bootloader ..... 13

11 Machine Learning ..... 14

12 Examples ..... 15

13 Boards and External Devices ..... 16

14 Other Gecko Platform Software Components ..... 17

15 RAIL Library ..... 18

## 1 CMSIS Device

### 1.1 New Items

#### Added in release 4.2.0.0

- Added support for EFR32xG25 devices
- Added support for EFR32xG21 Rev. C devices
- Added support for the BGM220SC23HNA module
- Added support for the MGM240SA22VNAX module
- Added support for the MGM240SD22VNAX module
- Added support for the BGM240SA22VNAX module
- Added support for the BGM240SB22VNAX module
- Added support for the BGM241SD22VNAX module

### 1.2 Improvements

None

### 1.3 Fixed Issues

#### Fixed in release 4.2.0.0

ID #	Description
1059733	ARMCC assembly startup files for Series 0 and Series 1 devices have been removed from GSDK since they have not been supported since GSDK v2.7
1064407	The PLL0, which provides an accurate 48 MHz clock to the USB, has been renamed for USBPLL0 in the EFR32xG25 header files.
1021831	Added EMU_RSTCAUSE_SETAMPER bit in device headers of EFR32xG21, EFR32xG23, EFR32xG24 and EFR32xG24 devices. This bit is asserted following a reset due to a tampering event detection.
1015647	Fixed the EXT_IRQ_COUNT macro value to match the number of external NVIC internal interrupt sources for EZR32HG, EZR32LG and EZR32WG devices.
1059733	ARM Startup files for Series 0 and Series 1 devices have been removed from GSDK since they have not been supported since GSDK v2.7

### 1.4 Known Issues in the Current Release

None

### 1.5 Deprecated Items

None

### 1.6 Removed Items

None

## 2 Peripherals

### 2.1 New Items

#### Added in release 4.2.0.0

- Added support for EFR32xG21 Rev. C in peripheral drivers (support for IADC internal voltage reference)
- Added support for the ETAMPDET peripheral
- The CMU\_CLOCK\_SELECT\_SET macro was added as an alternative to the function CMU\_ClockSelectSet, and may be used to reduce code size.
- Added new DisSyncOut field to TIMER\_Init\_TypeDef structure. This field can be used to disable the Timer's ability to start/stop/reload other timers.
- Added APIs to managed EFP interrupt in the EMU driver.
- Added APIs to access the HFXO CTune value in the CMU driver.

### 2.2 Improvements

#### Changed in release 4.2.0.0

- Added documentation for EMU\_DCDCXxxx() functions
- Improved Eusart\_Rx function when to account for Rx FIFO watermark

### 2.3 Fixed Issues

#### Fixed in release 4.2.0.0

ID #	Description
1043460	Fixed IADC_calcTimebase function to use the correct clock source. Time base calculation is now based off the correct clock source CLK_SRC_ADC rather than previous CLK_CMU_ADC. IADC is initialized with the correct time base and it is no longer required to manually set the correct time base value after initializing the IADC.
1037225	Fixed an issue where the EM4WU GPIO pin mode was configured as InputPull instead of InputPullFilter when configuring the EM4WU External Interrupt.
1033757	Device can still execute instructions after executing Enter_EM4() function is addressed with a new EMU_EnterEM4Wait() function. It waits after an EM4 entry request and makes sure no other code can run between the request and the moment the CPU is actually shut down.
1020645	Fixed EMU_BoostExternalShutdownEnable() API, BOOSTENCTRL bit logic was reversed.
1019940	Fixed EMU_RamPowerDown() end parameter behavior.
845272	Fixed a bug where the high-accuracy IADC offset correction calculation was wrong in the IADC initialization routine.
845232	Fix issue where the interrupts of the EFP would still be enabled after de-initializing the EFP driver.
1022566	Removed dmadrv_baremetal sample application for BRD2204C because it does not use usart0 peripheral for vcom.

### 2.4 Known Issues in the Current Release

None

### 2.5 Deprecated Items

None

### 2.6 Removed Items

None

## 3 Drivers

### 3.1 New Items

None

### 3.2 Improvements

None

### 3.3 Fixed Issues

#### Fixed in release 4.2.0.0

ID #	Description
811009	Implemented KEYSKAN_E301 fix for EFR32xg2x devices (fix for Keyscan interrupts not cleared on unused rows).

### 3.4 Known Issues in the Current Release

None

### 3.5 Deprecated Items

None

### 3.6 Removed Items

None

## 4 Services

### 4.1 New Items

#### Added in release 4.2.0.0

- Added a new Device Initialization RFFPLL service to handle RFFPLL peripheral initialization.
- Added new API to iostream: `sl_iostream_vprintf()`

### 4.2 Improvements

#### Changed in release 4.2.0.0

- Added support for 64-bit timestamps in sleeptimer wall clock APIs.
- Added the ability for sleeptimer service to use high frequency TIMER/WTIMER peripherals.
- `sl_device_init_hfxo()` will now use the `CMU_HFXOINIT_EXTERNAL_SINE` default settings if the "Device Init: HFXO" component's mode configuration is set to "External sine wave".
- Changed IOStream Uart interfaces reception to use DMA instead of receiving byte per byte.

### 4.3 Fixed Issues

#### Fixed in release 4.2.0.0

ID #	Description
852037	Periodic sleeptimers no longer drift over time when using milliseconds as the time base.
1019822	Fixed <code>sl_sleeptimer_get_datetime()</code> so it returns time in Standard Time to match <code>sl_sleeptimer_set_datetime()</code> which sets the timezone
1073997	Fixed <code>sl_sleeptimer_convert_unix_time_to_ntp()</code> to return an error when invalid time parameter is passed.
1068039	Fixed internal HFXO Manager settings applied when enabling <code>SL_HFXO_MANAGER_SLEEPY_CRYSTAL_SUPPORT</code> .
818102	Updated critical section used in Power Manager to explicitly use <code>PRIMASK</code> . This fixes an issue where the CPU would not wake up from sleep if <code>em_core</code> critical section are configured to use <code>BASEPRI</code> .
937666	Fixed IOStream Flush UART functionality for EUSART peripheral.
1065570	Fixed a bad usage of an enum during the preprocessor into the IOStream UART component

### 4.4 Known Issues in the Current Release

Issues in bold were added since the previous release.

ID #	Description
<b>1078350</b>	<b>Increased Interrupt latency due to IOStream UART DMA integration</b>

### 4.5 Deprecated Items

None

### 4.6 Removed Items

None

## 5 CPC

### 5.1 New Items

#### Added in release 4.2.0.0

- New CPC Protocol version; CPCd and Secondary must be updated.
- Encryption can be disabled per endpoint; dictated by the secondary.
- Added new functionality to retrieve libcpc the firmware application version and the library version.
- Added new asynchronous event notification mechanism to libcpc.
- Added new API in libcpc to set endpoint options with type safety.
- libcpc's wrapper in Rust.
- libcpc instances are limited to one per task.

### 5.2 Improvements

#### Changed in release 4.2.0.0

- Improved CPC Secondary UART drivers' reliability and recovery when the hardware flow control is disabled.
- libcpc had a few changes when errors occur. Instead of returning -1 and setting "errno", it now returns negative values; negative values of "errno".
- Few improvements to cpcd cmake file; how to retrieve mbedtls library and default compiler flags.
- Allow overriding socket directory / config path via CMAKE.
- Reduced minimum I-Frame retransmit timeout which also increase overall performance.
- Enhanced the tracing of the CPCd EZSP driver, used to send a firmware update to a CPC secondary using the Ember bootloader via SPI.
- CPCd can run on latest version of Android.
- Improved error reporting on bind failure.
- CPCd default binding key file location has been modified for "~/cpcd/binding.key".
- Prevent clients from connecting if CPCd is not started in normal mode.
- CPCd displays a warning if run with root privileges.
- Improved CPCd's error handling when the bootloader interface is not present, and a firmware upgrade is requested.
- Improved CPCd config parser to allow comments on the same line.

### 5.3 Fixed Issues

#### Fixed in release 4.2.0.0

ID #	Description
839674	Fixed in libcpc, the state returned by <code>cpc_get_endpoint_state()</code> after <code>cpc_endpoint_close()</code> has been called.
1040127	CPC security failed to initialize on EFR32MG13 and MG14 series parts. To work around this issue, <code>mbedtls_entropy_adc()</code> has been added as entropy source for these parts.
1057885	Fixed in libcpc, an issue that prevented users to call <code>cpc_restart()</code> again once it failed.
1064508	Fixed Secondary UART-EUSART driver with Hardware Flow control disabled and the security enabled.
1066686	Fixed a potential socket leak into <code>cpc_init()</code> when the daemon was not started.
1068063	Fixed an issue where the CS signal would not be de-asserted after successfully sending an SPI to the secondary device.
1066273	Fixed an issue where a retransmit from the secondary could cause an endpoint to close because the decryption would fail.
1067736	Fixed race condition with security endpoint when the client is actively connecting.

## 5.4 Known Issues in the Current Release

None

## 5.5 Deprecated Items

None

## 5.6 Removed Items

None



---

## 6 Common

### 6.1 New Items

None

### 6.2 Improvements

#### Changed in release 4.2.0.0

- Linker sections are sorted by alignment to improve memory usage

### 6.3 Fixed Issues

None

### 6.4 Known Issues in the Current Release

None

### 6.5 Deprecated Items

None

### 6.6 Removed Items

None

## 7 Middleware

### 7.1 New Items

None

### 7.2 Improvements

#### Changed in release 4.2.0.0

- Updated GLIB components to allow creation or use of a custom display implementation.
- Added configuration file to GLIB to reduce the memory footprint.

### 7.3 Fixed Issues

#### Fixed in release 4.2.0.0

ID #	Description
1015841	Fixed C++ compiler error with Glib.

### 7.4 Known Issues in the Current Release

None

### 7.5 Deprecated Items

None

### 7.6 Removed Items

None

## 8 Security

### 8.1 New Items

#### Added in release 4.2.0.0

- Updated the Mbed TLS library to version 3.2.1 with support for Certificate-Based Authentication & Pairing (CBAP).
- Added support for the TrustZone PSA initial attestation service. The Secure Key Library PSA attestation private key is stored in ITS with the UID 0xFFFFFFFFFFFFFFFF for Vault Mid devices. Hence, this UID should not be used for other purposes when the attestation service is enabled.
- Added RTOS support for the TrustZone Secure Key Library (TZ SKL) and TrustZone Gecko Bootloader. The TrustZone NSC interfaces support only one single thread to enter the secure libraries at any time by using a mutex, implemented with the CMSIS RTOS2 API. That is, there is no multi-thread concurrency allowed inside the secure libraries. The NonSecure application can run multiple threads concurrently. Currently FreeRTOS and MicriumOS are supported.
- Added ETAMPDET tamper source to SE manager for xG25.
- Added `sl_se_get_tamper_reset_cause()` function to SE Manager, available for Secure Vault High devices. The function lets the user find out if the last reset was caused by a Tamper event and which Tamper source caused the reset. Requires SE firmware version 2.2.1.
- `sl_se_get_otp_version()` is now available for VSE devices (as well as HSE devices). Requires VSE firmware version 2.2.1 / 1.2.14.
- Added support for non-blocksize input for AEAD multipart (fixed in GSDK version 4.1.1.0)
- Added support for partially overlapping input buffers for AEAD multipart (fixed in GSDK version 4.1.1.0)
- Added driver support for CCM multipart on xG21 devices (fixed in GSDK version 4.1.1.0)

### 8.2 Improvements

#### Changed in release 4.2.0.0

- Added a new version of the ITS driver (v3) in order to optimize the key look up time, especially for applications with more than 100 keys. ITS V3 uses simple PRNG with UID as a seed to create a hash-map-like structure. Note that NVM3 ID range was changed from region starting at 0x83100 to region ending with 0x870ff. We provide an upgrade path for the devices that already use the ITS driver. Note that after upgrading to ITS driver V3, `SL_PSA_ITS_USER_MAX_FILES` cannot be changed. Also note, that upgrade can take some time (more than 1min for 1000 files). New config options were added:
  - `SL_PSA_ITS_SUPPORT_V2_DRIVER` - This can be set to 0 if the device has never used ITS driver before in GSDK 4.1.x and earlier, or the keys have been already migrated to v3, and remove the unused code.
  - `SL_PSA_ITS_SUPPORT_V3_DRIVER` - This can be set to 1 if the device has never used ITS driver before in GSDK 4.1.x and earlier. This configuration option will add support for V3 driver, and provide an upgrade path from V1/V2. For devices that are not able to upgrade to ITS driver V3, we recommend disabling it, and using the previous version of the ITS driver.

The downgrade path of the ITS driver to an earlier version is not provided.

- PSA Crypto components have now been updated to reflect the addition of Curve25519 support on xG21A and xG23A devices. Users that depend on this functionality and are running SE firmware versions older than 1.2.10 and 2.1.7, respectively, are recommended to update their firmware (preferred) or manually add the ``Platform|Security|Mbed TLS|Elliptic Curves|Curve25519`` component to their project.
- Added components for use of PKCS #5 and #12 modules in Mbed TLS
- Add support for configuring dynamic memory allocation functions in Mbed TLS via SLC components.
- Add support for configuration of alternative threading support in Mbed TLS (aka `MBEDTLS_THREADING_ALT`) via SLC components.
- Changed the TrustZone root key automatic key renewal. The key is now only renewed on Device Erase.
- TRNG handling logic changed to reduce idle current consumption for xG22 in EM0/1.
- Added PSA API documentation links to Mbed TLS SLC components

## 8.3 Fixed Issues

### Fixed in release 4.2.0.0

ID #	Description
1074038	<p>The AES-CTR one-shot encryption function of the PSA SE driver (<code>sli_se_driver_cipher_encrypt</code>) may fail when operating on input data that are not multiples of 16 bytes, and the <code>alg</code> argument is <code>PSA_ALG_CTR</code> or <code>PSA_ALG_CCM_STAR_NO_TAG</code>. The cipher oneshot encryption function of the PSA Crypto API <code>psa_cipher_encrypt</code> generates random IV values and subsequently calls <code>sli_se_driver_cipher_encrypt</code>. The failure depends on the combination of cipher key and random IV, where some random IV values may cause an incorrect ciphertext.</p> <p>The bug does not have exploitable properties and is not considered to be a security vulnerability.</p> <p>Affected devices are HSE-based devices (series-0/1 and VSE not affected).</p> <p>Affected SDK versions are 3.1.0 - 3.1.2, 3.2.0 - 3.2.3, 4.0.0 - 4.02 and 4.1.0 - 4.1.3</p>
937813	<p>Fixed an issue when the application requests random data and the radio is off, uninitialized or malfunctioning, then no entropy is available for the entropy accumulator of Mbed TLS and consequently the PRNGs (CTR-DRBG and HMAC-DRBG). The fix implements a fallback to request entropy from the ADC if the radio returns 0 bytes of entropy. The prerequisite is that the user must configure the ADC as entropy source. (Fixed in GSDK version 4.1.1.0)</p>
845005	<p>Fixed issue on EFR32xG23 when DCI became unresponsive after running OTP initialization and Power-on-reset. In API function <code>sl_se_init_otp</code> reject setting reserved tamper sources to tamper levels other than "ignore" during OTP initialization by system manufacturer. (Fixed in GSDK version 4.1.1.0)</p>

## 8.4 Known Issues in the Current Release

Issues in bold were added since the previous release.

ID #	Description	Workaround
	<p><b>The platform security software support has been moved from the folder <code>util/third_party/crypto</code> to <code>platform/security</code>. The submodules <code>mbedtls</code> and <code>trusted-firmware-m</code> are now located in <code>util/third_party/</code>.</b></p>	<p><b>This should not affect any projects that are using SLC components. However, if your project is not based on SLC components (which can be the case especially for projects that were created before Gecko SDK v3.0), you may need to update the source file locations in the project files.</b></p>

## 8.5 Deprecated Items

None

## 8.6 Removed Items

### Removed in release 4.2.0.0

- [Remove deprecated multipart APIs with tag `SL\_DEPRECATED\_API\_SDK\_3\_3`:](#)
  - Deprecated CMAC multipart API has been removed.
  - Deprecated GCM multipart API has been removed.
  - Deprecated HASH multipart API has been removed.

## 9 Operating System

No changes

## 10 Gecko Bootloader

### 10.1 New Items

None

### 10.2 Improvements

#### Changed in release 4.2.0.0

- Added automated support for executing post-build actions.
- Added support for upgrading from storage slots in a sequential order in a multi-slot configuration in an absence of a bootloader list as opposed to an early exit. A configuration option is available in the Bootloader Storage Slot Setup component to enable/disable validation of the slot layout in case of a multi-slot configuration.

### 10.3 Fixed Issues

#### Fixed in release 4.2.0.0

ID #	Description
1043067	Added fix for XModem idle Timeout macro set to a non-default value in Bootloader - UART XMODEM sample app.
00289194	Added fix for Bootloader - SoC Bluetooth in-place OTA DFU application to display only for series 1 devices in Simplicity Studio.
00286863	Fixed an issue where the upgrade image size calculated was off by 4 bytes due to the CRC32 checksum that got appended to the image after the signature (fixed in version 4.1.1.0).

### 10.4 Known Issues in the Current Release

None

### 10.5 Deprecated Items

None

### 10.6 Removed Items

None

---

## 11 Machine Learning

### 11.1 New Items

None

### 11.2 Improvements

#### Changed in release 4.2.0.0

- Added support for more tflite micro operators in the slc generator script that autogenerates the OpResolver code.

### 11.3 Fixed Issues

None

### 11.4 Known Issues in the Current Release

None

### 11.5 Deprecated Items

None

### 11.6 Removed Items

None

## 12 Examples

### 12.1 New Items

- Added ml\_blink example showing a minimal tflite micro example blinking a led using a machine learning model. Meant to be used as a starting point for machine learning development.
- Added ml\_magic\_wand example. This example is based on a TensorFlow Lite micro example, but with an improved model to make gesture detection better.

### 12.2 Improvements

- Fixed suppression issue in voice\_control\_light and audio\_classifier example, improving the classification stability.

### 12.3 Fixed Issues

ID #	Description
1075130	Fixed issue in the ml_magic_wand example where the tflite arena size was too small.

### 12.4 Known Issues in the Current Release

Issues in bold were added since the previous release. If you have missed a release, recent release notes are available on <https://www.silabs.com/products/software>.

ID #	Description	Workaround
664803	<b>Se_manager</b> and <b>psa_crypto</b> sample apps do not work correctly in Simplicity Studio 5's launch console.	In the launch console, change the line terminator selection to None.

### 12.5 Deprecated Items

None

### 12.6 Removed Items

- Removed tflite\_micro\_hello\_world example, this example was replaced by the ml\_blink example.
- Removed tflite\_micro\_magic\_wand example, this example was replaced by the ml\_magic\_wand example.



## 13 Boards and External Devices

### 13.1 New Items

#### Added in release 4.2.0.0

Added support for the following new OPNs:

- BRD4318A
- BRD4335A

### 13.2 Improvements

None

### 13.3 Fixed Issues

None

### 13.4 Known Issues in the Current Release

None

### 13.5 Deprecated Items

None

### 13.6 Removed Items

None

## 14 Other Gecko Platform Software Components

No changes

## 15 RAIL Library

### 15.1 New Items

#### Added in release 4.2.0.0

- Added HFXO temperature compensation in RAIL on platforms that support `RAIL_SUPPORTS_HFXO_COMPENSATION`. This feature can be configured with the new `RAIL_ConfigHFXOCompensation()` API. The user will also need to be sure to handle the new `RAIL_EVENT_THERMISTOR_DONE` event to trigger a call to `RAIL_CalibrateHFXO` to perform the compensation.
- Added options in "RAIL Utility, Protocol" component to control whether Z-Wave, 802.15.4 2.4 GHz and Sub-GHz, and Bluetooth LE are enabled so that the user can save space in their application by disabling unused protocols.
- Added a new API `RAIL_ZWAVE_PerformIrcal` to help perform an IR calibration across all the different PHYs used by a Z-Wave device.
- Added 40 MHz crystal support on EFR32xG24 devices to the "RAIL Utility, Built-in PHYs Across HFXO Frequencies" component.
- Added support for IEEE 802.15.4 fast RX channel switching with the new `RAIL_IEEE802154_ConfigRxChannelSwitching` API on supported platforms (see `RAIL_IEEE802154_SupportsRxChannelSwitching`). This feature allows us to simultaneously detect packets on any two 2.4 GHz 802.15.4 channels with a slight reduction in overall sensitivity of the PHY.
- Added support for the BGM220SC23HNA2 module.
- Added a new Thermal Protection feature, on platforms that support `RAIL_SUPPORTS_THERMAL_PROTECTION`, to track temperature and prevent transmits when the chip is too hot.
- Added new table-based OFDM and FSK PAs for EFR32xG25 based devices. The output power of these can be modified through a new customer provided look-up table. Ask support or look for an updated app note on how to configure the values in this table for your board.
- Added support for the MGM240SA22VNA, BGM240SA22VNA, and BGM241SD22VNA modules and updated the configurations for the BGM240SB22VNA, MGM240SB22VNA, and the MGM240SD22VNA.

### 15.2 Improvements

#### Changed in release 4.2.0.0

- The `RAIL_ConfigRfSenseSelectiveOokWakeupPhy()` will now return an error when run on the EFR32xG21 platform because this device cannot support the wakeup PHY.
- Updated the `pa_customer_curve_fits.py` helper script to accept floating point value for the maximum power argument, similar to the increment argument.
- Added support in "RAIL Utility, Coexistence" component for configuring priority options when directional priority is enabled but no static priority GPIO is defined.
- Broke up some EFR32xG12 802.15.4 dynamic FEC code to save code size for Zigbee and Bluetooth LE, which never need this functionality.
- Remove "RAIL Utility, Coexistence" component dependency from the RAIL Utility, Coulomb Counter component.
- The `RAIL_PrepareChannel()` function has been made dynamic multiprotocol safe and will no longer return an error if called when your protocol is inactive.

### 15.3 Fixed Issues

#### Fixed in release 4.2.0.0

ID #	Description
843708	Moved function declarations from <code>rail_features.h</code> to <code>rail.h</code> to avoid a convoluted include dependency order.
844325	Fixed <code>RAIL_SetTxFifo()</code> to properly return 0 (error) rather than 4096 for an undersized FIFO.
845608	Fixed an issue with the <code>RAIL_ConfigSyncWords</code> API when using certain underlying demodulator hardware on EFR32xG2x parts.
851150	Fixed an issue on EFR32xG2 series devices where the radio would trigger <code>RAIL_ASSERT_SEQUENCER_FAULT</code> when PTI is used and GPIO configuration is locked. GPIO configuration can only be locked when PTI is disabled. See <code>RAIL_EnablePti()</code> for further information.

ID #	Description
857267	Fixed an issue when using the "RAIL Utility, Coexistence" component with TX abort, the signal identifier feature and DMP.
1015152	Fixed an issue on EFR32xG2x devices where RAIL_EVENT_RX_FIFO_ALMOST_FULL or RAIL_EVENT_TX_FIFO_ALMOST_EMPTY could trigger improperly when the event is enabled or the FIFO is reset.
1017609	Fixed an issue where PTI appended information could be corrupted when RAIL_RX_OPTION_TRACK_ABORTED_FRAMES is in effect when RAIL_IDLE_FORCE_SHUTDOWN or RAIL_IDLE_FORCE_SHUTDOWN_CLEAR_FLAGS is used. Also clarified that RAIL_RX_OPTION_TRACK_ABORTED_FRAMES is not useful with coded PHYs.
1019590	Fixed an issue when using the "RAIL Utility, Coexistence" component with BLE where the <code>sl_bt_system_get_counters()</code> function would always return 0 for GRANT denied counts.
1019794	Eliminated compiler warning in "RAIL Utility, Initialization" component when few of its features are enabled.
1023016	Fixed an issue on EFR32xG22 and newer chips where waits in between radio activity would consume slightly more power than necessary after the first 13 ms. This was especially noticeable when using <code>RAIL_ConfigRxDutyCycle</code> with large off time values.
1029740	Fixed issue where <code>RAIL_GetRssi()/RAIL_GetRssiAlt()</code> could return a "stale" RSSI value (the value was from previous RX state instead of the current one) if called quickly upon entering receive.
1040814	Added support to the "RAIL Utility, Coexistence" component for configuring the coexistence request priority on sync detect when using BLE.
1056207	Fixed an issue with IQ sampling when using the "RAIL Utility, AoX" component with only 0 or 1 antennas selected.
1062712	Fixed an issue where the "RAIL Utility, Coexistence" component would not always update request states correctly, which could lead to missed events triggered by new requests.
1062940	Prevented the "RAIL Utility, Coexistence" component from aborting BLE transmits when <code>SL_RAIL_UTIL_COEX_BLE_TX_ABORT</code> is disabled.
1063152	Fixed an issue where radio reception would not be fully cleaned up when a receive error occurred with receive state transitions set to idle on error but transmit on success, a configuration mostly associated with BLE. On the EFR32xG24 this could cause a SYNTH calibration to not be properly restored and eventually cause the radio to stop working.

## 15.4 Known Issues in the Current Release

Issues in bold were added since the previous release.

ID #	Description	Workaround
	Using direct mode (or IQ) functionality on EFR32xG23 requires a specifically set radio configuration that is not yet supported by the radio configurator. For these requirements, reach out to technical support who could provide that configuration based on your specification	
641705	Infinite receive operations where the frame's fixed length is set to 0 are not working correctly on the EFR32xG23 series chips.	
732659	On EFR32xG23: <ul style="list-style-type: none"> <li>• Wi-SUN FSK mode 1a exhibits a PER floor with frequency offsets around <math>\pm 8</math> to 10 KHz</li> <li>• Wi-SUN FSK mode 1b exhibits a PER floor with frequency offsets around <math>\pm 18</math> to 20 KHz</li> </ul>	

## 15.5 Deprecated Items

None

---

## 15.6 Removed Items

None

# Simplicity Studio

One-click access to MCU and wireless tools, documentation, software, source code libraries & more. Available for Windows, Mac and Linux!



**IoT Portfolio**  
[www.silabs.com/IoT](http://www.silabs.com/IoT)



**SW/HW**  
[www.silabs.com/simplicity](http://www.silabs.com/simplicity)



**Quality**  
[www.silabs.com/quality](http://www.silabs.com/quality)



**Support & Community**  
[www.silabs.com/community](http://www.silabs.com/community)

## Disclaimer

Silicon Labs intends to provide customers with the latest, accurate, and in-depth documentation of all peripherals and modules available for system and software implementers using or intending to use the Silicon Labs products. Characterization data, available modules and peripherals, memory sizes and memory addresses refer to each specific device, and "Typical" parameters provided can and do vary in different applications. Application examples described herein are for illustrative purposes only. Silicon Labs reserves the right to make changes without further notice to the product information, specifications, and descriptions herein, and does not give warranties as to the accuracy or completeness of the included information. Without prior notification, Silicon Labs may update product firmware during the manufacturing process for security or reliability reasons. Such changes will not alter the specifications or the performance of the product. Silicon Labs shall have no liability for the consequences of use of the information supplied in this document. This document does not imply or expressly grant any license to design or fabricate any integrated circuits. The products are not designed or authorized to be used within any FDA Class III devices, applications for which FDA premarket approval is required or Life Support Systems without the specific written consent of Silicon Labs. A "Life Support System" is any product or system intended to support or sustain life and/or health, which, if it fails, can be reasonably expected to result in significant personal injury or death. Silicon Labs products are not designed or authorized for military applications. Silicon Labs products shall under no circumstances be used in weapons of mass destruction including (but not limited to) nuclear, biological or chemical weapons, or missiles capable of delivering such weapons. Silicon Labs disclaims all express and implied warranties and shall not be responsible or liable for any injuries or damages related to use of a Silicon Labs product in such unauthorized applications.

**Note: This content may contain offensive terminology that is now obsolete. Silicon Labs is replacing these terms with inclusive language wherever possible. For more information, visit [www.silabs.com/about-us/inclusive-lexicon-project](http://www.silabs.com/about-us/inclusive-lexicon-project)**

## Trademark Information

Silicon Laboratories Inc.<sup>®</sup>, Silicon Laboratories<sup>®</sup>, Silicon Labs<sup>®</sup>, SiLabs<sup>®</sup> and the Silicon Labs logo<sup>®</sup>, Bluegiga<sup>®</sup>, Bluegiga Logo<sup>®</sup>, EFM<sup>®</sup>, EFM32<sup>®</sup>, EFR, Ember<sup>®</sup>, Energy Micro, Energy Micro logo and combinations thereof, "the world's most energy friendly microcontrollers", Redpine Signals<sup>®</sup>, WiSeConnect, n-Link, ThreadArch<sup>®</sup>, EZLink<sup>®</sup>, EZRadio<sup>®</sup>, EZRadioPRO<sup>®</sup>, Gecko<sup>®</sup>, Gecko OS, Gecko OS Studio, Precision32<sup>®</sup>, Simplicity Studio<sup>®</sup>, Telegesis, the Telegesis Logo<sup>®</sup>, USBXpress<sup>®</sup>, Zentri, the Zentri logo and Zentri DMS, Z-Wave<sup>®</sup>, and others are trademarks or registered trademarks of Silicon Labs. ARM, CORTEX, Cortex-M3 and THUMB are trademarks or registered trademarks of ARM Holdings. Keil is a registered trademark of ARM Limited. Wi-Fi is a registered trademark of the Wi-Fi Alliance. All other products or brand names mentioned herein are trademarks of their respective holders.



Silicon Laboratories Inc.  
400 West Cesar Chavez  
Austin, TX 78701  
USA

[www.silabs.com](http://www.silabs.com)